Operator Manual

FB3000 II Series Instrument

The Next Generation with Intalogix™ Technology

51220

© 2010 by Fairbanks Scales, Inc.
All rights reserved

Revision 1 02/10

Amendment Record

FB3000 II Series Instrument With Intalogix™ Technology

FB3000 II KERNEL PROGRAM

OPERATORS MANUAL

DOCUMENT 51220

Manufactured by Fairbanks Scales Inc.
821 Locust Street
Kansas City, Missouri 64106

Created	02/2010	
Revision 1	02/2010	Documentation Release

© Copyright 2010

This document contains proprietary information protected by copyright. All rights are reserved; no part of this manual may be reproduced, copied, translated or transmitted in any form or by any means without prior written permission of the manufacturer.

Trademarks

IBM, EGA, VGA, XT/AT, OS/2 and PS/2 are registered trademarks of International Business Machine Corporation.
Award is a trademark of Award Software International, Inc. RTL is a trademark of Realtek Semi-Conductor Co., Ltd.
VIA is a trademark of VIA Technologies, Inc.
Winbond is a trademark of Winbond Technology, Inc.
CF and CompactFlash are trademarks of ScanDisk Corporation.
Microsoft, Windows, Windows NT, Windows XP, and MS-DOS are either trademarks or registered trademarks of Microsoft Corporation.
All other product names mentioned herein are used for identification purpose only and may be trademarks and/or registered trademarks of their respective companies.

Disclaimer

Every effort has been made to provide complete and accurate information in this manual. However, although this manual may include a specifically identified warranty notice for the product, Fairbanks Scales makes no representations or warranties with respect to the contents of this manual, and reserves the right to make changes to this manual without notice when and as improvements are made.

It is the responsibility of the requesting party to develop, maintain, install, and connect networking devices and general network connectivity as it applies to the originating party's network. No warranty or guarantee, expressed or implied, concerning the network, its design, its installation, or operational characteristics has been offered by Fairbanks Scales. Fairbanks Scales shall not be liable for any loss, damage, cost of repairs, incidental or consequential damages of any kind, whether or not based on express or implied warranty, contract, negligence, or strict liability arising in connection with the design, development, installation, or use of an intended network.

Table of Contents

SECTION 1: GENERAL INFORMATION 6

1.1. Introduction 6

1.1.1. The FB3000 II 6

1.1.2. Kernel Description 6

1.2. Technical Specifications 8

1.3. FEATURES 10

SECTION 2: CUSTOMER RESPONSIBILITY 12

2.1. Users' Responsibilities 12

2.2. Equipment/ Component Care 13

SECTION 3: KEY FUNCTIONS AND MENUS 14

3.1. Key Functions 14

3.2. GENERAL PROGRAMMING MENUS 16

3.3. Backing up and Saving program Changes to a Folder 17

SECTION 4: INPUT / OUTPUT (I/O) 18

4.1. Introduction 18

4.2. 4.2. Configure Output 18

4.2.1. Introduction 18

4.2.2. Configuring an Output Data String 18

4.2.3. Two Methods of Formatting 18

4.2.4. Load Default Data Protocols 19

4.2.5. Load the Default COM Settings 19

4.2.6. Customizing the Output Data Strings 21

4.2.7. Steps in Customizing 21

4.2.8. ASCII and Text Data Character Types 24

4.2.9. Other Data String Customization 25

4.3. 20 mA Serial Current Loop Programming 31

4.4. IP Network Output 33

4.4.1. P Setup Menu Overview 33

4.4.2. IP Network Output Setup Instructions 35

4.4.3. Testing the IP Network Output 38

SECTION 5: OPERATION 39

5.1. SYSTEM BOOT-UP PROCEDURE 39

5.2. Viewing Options 40

5.3. Gross Weighing 40

5.3.1. Using the Display Screen Function Buttons 41

5.4. Application Shut-Down Procedure 42

5.5. System Shutdown Procedure 43

SECTION 6: SERVICE & MAINTENANCE 44
6.1. Troubleshooting 44
6.2. Remote Service and Diagnostics 45
6.2.1. Opening the VNC Connection 45
APPENDIX I: GPIO PORT 46
APPENDIX II: SYSTEM RESOURCE 48
APPENDIX III: DATA OUTPUT 52
APPENDIX IV: NETWORK COMMAND FUNCTIONS 58
APPENDIX V: PROGRAMMING THE WATCHDOG TIMER 59
APPENDIX VI: KERNEL 20MA CODES 60
APPENDIX VII: SOCKS INFORMATION 61
APPENDIX VIII: REMOTE FUNCTIONS 65
APPENDIX IX: ASCII CODES 66

Section 1: General Information

1.1. INTRODUCTION

The Fairbanks FB3000 II Solutions Series instrument is a powerful, versatile, indicator which has flexibility, open architecture, and integrated capabilities of many computer functions. With these abilities, the FB3000 II collects, processes, and transmits data through RS232, RS485, RS422 serial ports, USB, parallel port, and PCI 10/100 Mbs Ethernet interfaces.

1.1.1. The FB3000 II

Current FB3000 II Units include the following applications:

- **NewScale Program**
- **Kernel Weight Server Program**
- **In/Out Application**
- **LabelBank Application**
- **Highway System Application**
- **SoftBatch Application**
- **Interact Inside Program**

1.1.2. Kernel Description

The FB3000 II Kernel is weight serving program for all FB3000 II applications. It provides the core metrological functions for all the applications. It includes the following additional features:

- Multicasting capability to monitor and operate multiple scales across a network.
- Backup and Restore feature.
- Programmable Serial Communication Outputs

The FB3000 II KERNEL is a Fairbanks-developed Weight Server Program

Kernel Description, Continued

- Intalogix equipped units have load cell diagnostics features for easier troubleshooting capabilities.
- An integrated e-mail client is configurable to alert a service organization or individual of a problem prior to total failure.
  - These error notifications include such warnings as load cell failure, low memory, calibration change,
  - Flash memory error, and several other notifications to keep the proper individuals informed of the scale's operating condition.
  - Uses the customer's existing email infrastructures, and requires a connection to the customer's Network.
  - Requires a connection to the customer's PC Network.
- The **FB3000 II** Kernel program is designed to function with platform scales equipped with the following:
  - Intalogix™ Technology
  - Analog Load Cells
  - Mettler Toledo DigiTol™ Load Cells.
- The instrument ***can control up to eight (8) scales***.
- Multi-scale ***viewing capability of up to four (4) scales*** at once is also a standard feature.
- The FB3000 II Kernel uses the following Modes of Operation:
  - Gross Only
  - GTN (Gross / Tare / Net)

1.2. TECHNICAL SPECIFICATIONS

ENCLOSURE	• Painted Steel (NEMA 12) — Product 30070 • Stainless Steel (NEMA 12) — Product 30079 • Stainless Steel and Aluminum (NEMA 12) — Product 30077; 30078 • Stainless Steel (NEMA 4X) — Product 30079
PROCESSOR	1 GHz CPU
BIOS	Award® 512KB Flash BIOS
RAM	One DDR SO-DIMM memory socket up to 1GB
STORAGE	64 GB SSD (Solid State Drive)
OPERATING SYSTEM	Microsoft XP Pro™ Embedded with Service Pack 2
OUTPUTS	**Parallel Port** – One (1) bi-directional parallel port with SPP/ECP/EPP support. **Serial Ports** – One (1) RS-232/422/485 (scale interface), COM 2; Three (1) Board mounted RS232 (2) Case mounted RS232 ports, COM 3 and COM 4. **USB Ports** – Three (2) Board mounted ports, and One (1) external ports. **SVGA Port** – One (1) Board mounted SVGA display output.
KEYBOARD AND MOUSE INTERFACE	Supports PS2 or USB keyboards Supports PS2 or USB mice
PC/104 CONNECTOR	One (1) Board mounted PC/104 connector
DIGITAL I/O	Eight (8) internal digital inputs and outputs
ETHERNET INTERFACE	PCI 100/10 Mbps Ethernet interface with a female RJ45 connector. Complies with IEEE 802.3x Standards
DISPLAY	• 10.4” Color SVGA Color LCD-TFT; Full graphic support; 600 x 800 resolution • 10.4” Color SVGA Color DVI; 600 x 800 resolution (FB3000 II T models)
BATTERY	Lithium 3V/220mAH

1.2. TECHNICAL SPECIFICATIONS, CONTINUED

SCALE INTERFACE OPTIONS	• Intalogix Technology — External QMB Interface (**30433**) — External Intalogix Communication Board (**28330**) ▪ *Maximum of twenty (20) 1000 Ω or twelve (12) 350 Ω cells* — Dual External Intalogix Communication Board (**28333**) ▪ *Up to forty (40) 1000 Ω or twenty-four (24) 350 Ω cells* • Analog Technology — External Analog Load Cell Interface (**29646**) ▪ *Up to sixteen (16) 1000 Ω or ten (10) 350 Ω cells* — Dual External Analog Load Cell Interface (**30124**) ▪ *Up to sixteen (32) 1000 Ω or ten (20) 350 Ω cells* ▪ *Maximum of two (2) per FB3000 II.* — Internal PC104 Weight Controller (**27104**) ▪ *High Speed A/D* ▪ *Maximum of ten (10) 1000 ohm load cells per scale input* ▪ *Controls up to two (2) scales* ▪ *Provides passive 20mA serial output* ▪ *Provides passive 4-20mA analog output* ▪ *Maximum of two (2) per FB3000 II.*
ACCESSORIES	• Mini keyboard (**25498**) — PS2 – 87 key • NEMA 4 Rubberized keyboard (**27077**) — USB • Mouse (**26387**) — Two (2) button with scroll wheel — USB • Wall Bracket – Painted Steel (**26223**) • Wall Bracket – Stainless Steel (**26224**) • Compact Flash Card 32MB (**25853**) • SVP/ Uninterruptible Power Supply (UPS) (**15892**) — 500 VA Rating

1.2. TECHNICAL SPECIFICATIONS, CONTINUED

ACCESSORIES CONTINUED	• External Serial Port Relay Kit (**26727**) — Basic traffic light control (Interact) • 4-20mA analog and 20mA serial output (**27104**) — PC140 Weight Controller
POWER REQUIREMENTS	100 - 130 VAC @ 12A @ 60 Hz +/- 2 Hz — Separate and dedicated circuit. — Neutral to Ground voltage should be ≤ 0.2 vAC
ETL LISTED	• Conforms to UL STD 60950-1. • CAN/CSA C 22.2 NO.60950-1-03.
APPROVALS	• CC# 04-013; • MC# M-5552C

1.3. FEATURES

DIAGNOSTICS	Built-in self diagnostics reports on: • Calibration change • Time and date change • Remote access enabled • Routine maintenance required' • Flash memory error • Load cell ghosted • Load cell failure
LOAD CELL FLAG	Visual "flags" identify problem load cell(s) on diagnostic screen until flag is manually cleared to identify intermittent problems
LOAD CELL GHOSTING	Ability to electronically "mimic" or duplicate a failed load cell if equipped with Intalogix™ Interface for load cell communications (preventing system failure and/or shutdown)
REMOTE DIAGNOSTICS	Programmable Remote Diagnostic Utility provides remote diagnostics and configuration from any PC with proper authorization and access

1.3. FEATURES, CONTINUED

EMAIL ERROR REPORTING	Built-in email client for reporting error conditions such as the following: • Calibration change • Time and date change • Flash memory error • Remote access enabled • Routine maintenance required • Load cell ghosted • Load cell failure
ERROR DISPLAYING	Programming-selected display of error messages
BACKUP	Features the ability to backup information to optional Flash Memory card, network or USB pen drive
WEB BROWSER	Built-in browser allowing web access for software updates and web site viewing if desired

Section 2: Customer Responsibility

2.1. USERS' RESPONSIBILITIES

It is the customer/operator's responsibility to ensure the equipment provided by Fairbanks is operated within the parameters of the equipment's specifications and protected from accidental or malicious damage.

W A R N I N G !

Absolutely no physical, electrical or program modifications other than selection of standard options and accessories can be made by customers to this equipment

Repairs are performed by Fairbanks Scales Service Technicians and Authorized Distributor Personnel ONLY!

Failure to comply with this policy voids all implied and/or written warranties

2.2. EQUIPMENT/ COMPONENT CARE

- ✓ **Do not remove power** from this unit unless it is performed by the proper shut down method. Failure to comply with the proper shut down procedures can result in damage to the hard disk drive or data.
- ✓ The AC receptacle/outlet shall be located near the instrument and easily accessible.
- ✓ Electrical connections other than those specified may not be performed.
- ✓ Absolutely **no physical, electrical or program modifications** other than selection of standard options and accessories are to be made to this equipment.
  - – Electrical connections other than those specified may not be performed, and physical alterations (holes, etc.) are not allowed.
- ✓ The equipment consists of printed circuit assemblies which must be handled using proper ESD handling procedures.
  - – Replacement of individual components is not allowed.
  - – Any assemblies which are replaced must be properly packaged in ESD protective material if they are returned for replacement credit under a warranty condition.

Section 3: Key Functions and Menus

3.1. KEY FUNCTIONS

On-Screen Keyboard	External Keyboard	Description
Arrows	**Arrows**	• Navigates through the display. • Used also for scrolling.
Menu Button	**Esc**	• Changes the display to the **Operation Menu**. • Returns user to the previous menu.
Zero	**Pause Break**	Key(s) will **Zero the Scale.**
Print	**Prt Sc**	Prints a ticket. • In the **In/Out Device**, an **Inbound or Outbound Gross** ticket. • A Gross, Tare, Net ticket may also be printed. • In the **Weigh Only mode**, a Gross Weight ticket may be printed with a manually entered Tare and the Net will be calculated.

3.1. KEY FUNCTIONS, CONTINUED

On-Screen Keyboard	External Keyboard	Description
Units	**Scroll Lock**	Changes the units of weight displayed, depending on the selection made in the **Calibration Menu**.
0 to 9	**0 to 9**	Used to enter numeric data, such as tares and IDs.
Enter	**Enter**	Stores selections into memory during data entry or programming.
F1	**F1**	Toggles between the scales that are viewed and operated.
F2	**F2**	Unassigned
F3	**F3**	Unassigned
F4	**F4**	Unassigned
F5	**F5**	Toggles between the scale groups when more than four (4) scales are used.
F6	**F6**	Toggles between the **Operational Screen** and the **Multi-Scale Screen**, if more than one scale is being controlled.
	F7	Unassigned
	F8	Unassigned
	F9	Unassigned
	F10	• Service Usage only. !!Warning!! changing this items in this area can effect the proper operation of the scale.
	F11	Unassigned
	F12	Unassigned

The Kernel can be set up to operate in one of two **Modes of Operation,** depending upon the service programming:

- **Gross Weighing**
- **GTN (Gross / Tare / Net)**

Additional Windows Tips

- **ALT + F4 key** Shuts down the active program *immediately*
- **Windows Key + D** Moves to the **Desktop**
- **Windows Key + E** Opens **MS Windows Explorer™**

3.2. GENERAL PROGRAMMING MENUS

The programming menus which contain all of the parameters for the system are listed below.



Options Menu

This is the main menu, used to **gain access to other system menus for configuration and calibration**.

- It is accessible without a password by pressing the **MENU** key.
- Access provided for **Weights and Measures Official** to view the **Audit Trail** for calibration and configuration changes.
- Quick access to electronic **Operators' Manual.**



Configuration Menu

This menu is used to access **diagnostics utilities** and **communications programming.**

- *Optional programmable* password protection.

Service Menu

This menu is used to program the **metrological parameters of the system**, such as **scale capacity, calibration**, and **graduation size.**

- ***Must be*** password protected for all **Legal For Trade** applications.

The Service Menu functions are used by Fairbanks Authorized Service Personnel ONLY.



3.3. BACKING UP AND SAVING PROGRAM CHANGES TO A FOLDER

Each time a programming change is made to the Kernel Program, a **Backup Changes** popup window appears.



- The normal answer is **NO.**
- Either double-click the NO or click the MENU .

NOTE: *Save changes **ONLY WHEN** the programming change(s) are correct, and the system is proven to operate properly for all conditions.*

- For backing up the changes to a folder, click either the

  or on the **Weight Screen's keypad**, click the enter .

- Each file is saved by the date.
- (**yyyymmdd.BAK**).



IMPORTANT NOTE: *Backup* **EVERY** *Configuration change…* ***EVERY TIME!***

Section 4: Input / Output (I/O)

4.1. INTRODUCTION

Connectivity is one of the primary features of the FB3000 II and Kernel Weight Server program. The FB3000 II has multiple RS232 ports, USB ports, Ethernet port, and a Parallel port to name a few. This section will provide steps in order to connect the FB3000 II in a variety of manners to a variety of devices.

4.2. 4.2. CONFIGURE OUTPUT

4.2.1. Introduction

This menu selection provides a means to configure data strings protocols, configuration parameters, and output modes such as Continuous, Demand, Auto, To File, and Network.

4.2.2. Configuring an Output Data String

In order to interface an FB3000 II Instrument to software or a pre-existing peripheral device, such as a remote display, knowing their specific Output Data String is ***mandatory***.

- This allows the software or peripheral device to communicate with the FB3000 II.
- When adding to other manufacturer's devices, refer to their Service Manuals for Output Data String information.
- Interfacing with other manufacturer's software, refer to either a web site, Service Manual, or contact the manufacturer directly for the Output Data String information.

Fairbanks' current programming for setting up an **Output Data String** provides quick and easy flexibility for customizing the FB3000 II Serial Outputs.

4.2.3. Two Methods of Formatting

There are two methods to format an **Output Data String**.

1. Use one of the five (5) preconfigured **Load Defaults** under the **Load tab**.

2. Use the most similar **Load Default** as a basis for customizing an **Output Data String** which matches the manufacturer's company-specific configuration. This method is done in the **Build tab.**

4.2.4. Load Default Data Protocols

When programming a **Output Data String**, the Fairbanks' FB3000 II has five of the most commonly used pre-configurations, known as **Load Defaults**. These data strings are listed below:

Fairbanks	**<STX><A><B><C><GGGGGG><TTTTTT><CR>**
Toledo	**<STX><A><B><C><GGGGGG><TTTTTT><CR>**
Cardinal	**<CR><P><WWWWWW><m><SP><U><SP><g><SP><SP><ETX>**
Weightronix	**< ><M><WWWWWW>< ><U><CR><LF>**
Condec	**<STX><P><WWWWWWW><U><G><M><CR>**

4.2.5. Load the Default COM Settings

Follow these steps to configure the **Load Default** into the **Output Data String**.

3. From the **Weighing Application Window**, press the **MENU** button, from the Kernel Options Menu, select **Configuration Menu**.

4. Select **Configure Output**..



4.2.5. Load the Default COM Settings, Continued

5. Open the **Load** tab.
6. Select the **COM Port** to be configured.
7. Sect the appropriate **Load Default.**
8. Press the ✓OK button.



9. Open the **Port Settings** tab.
10. Program the **Baud Rate, Stop Bits**, and the **Parity** to the appropriate settings.



4.2.6. Customizing the Output Data Strings

The FB3000 II Kernel Weight Server program can also be customized to support numerous manufacturers software interfaces and peripheral devices. When programming a Data String Protocol not formatted as one of the ***Load Defaults***, the Output Data String must be ***programmed manually*** using the **Build, Tokens, and Weights Tabs.**

4.2.7. Steps in Customizing

Follow these steps to customize the **Output Data String**.

11. Locate the required **Output Data String** by viewing history from previous work completed with the customer, or by emailing and/or calling the company directly and asking their **IT Department** for this information.
12. Compare the required **Output Data String** with the five **Load Default** configurations.
13. Open the **Load** tab.
14. Select the **COM Port** to be configured.
15. Select the Load Default that most resembles the required Output Data String format.
16. Press the ✓OK button.



4.2.7. Steps in Customizing, Continued

17. Open the **Build** tab.



18. **Left-click** on the appropriate field to be generated within the specific data string, then select **Text.**

    – This adds a new **Text** box to the **Output Data String**.



19. Program a command within the **Data String**, either enter an **ASCII Character**, or **input text**.

    – When inputting ASCII Characters, ***always*** precede the message with "**0x...**" and the equivalent ASCII code up to 3 digits (*i.e.* **0x099**).

20. Open the **Port Settings** tab.

21. Program the **Baud Rate, Stop Bits**, and the **Parity** to the appropriate settings.



4.2.7. Steps in Customizing, Continued



Window Name	Description
CONFIGURE OUTPUT, — **Build Tab**	Configures the **data string protocol order**, written in **ASCII text.** By left-clicking in any item, a drop-down menu offers different parameters, or removes them. Text may be added to the data string by clicking in the **Value** field, then entering it. — Also by clicking into the **Data Type** box and choosing text from the drop down box.

4.2.8. ASCII and Text Data Character Types

There are two types of data configuration characters. Both have an important and have a specific function; both are used within the same data string. Both types are defined below.

ASCII (American Standard Code for Internet Interchange) Characters

- **Text Formatted Characters** are always written with a "**0x_ _ _** " prefix, which tells the **Kernel Program Read-me Trigger** to post it as text character (*i.e.* **0x120).**
- A code for information exchange between computers using a string of seven (7) binary digits represents each character.
- Each character identifies either a alphanumeric symbol (*i.e.* **065** = **A**, **066** = **B,** *etc.*) *or invokes an on-screen action (i.e.* **013** = **CR** = **C**arriage **R**eturn).
- One **Text Block** must be added to the Data String for each character before formatting it.
- The data entries use ***decimal-based ASCII character codes***.
- Complete ASCII Chart found in **Appendix IV.**

Text Formatted Characters

- A **Text** block must be added to the **Data String** before formatting the next character.
- These **Text Formatted Characters** are used to add a specific message to the Service Technician, and it is done in combination with the text and with other ASCII Text Characters.

4.2.9. Other Data String Customization



Window Name	Description
CONFIGURE OUTPUT — **Settings Tab**	**RS232 COM Port Drop-down** – Selects COM Port with its settings. **Data Transmission Options*** — **Continuous** [transmission] — **Demand** – Upon demand as a poll character is received — **Auto** – A transmission is sent when requested or when the transaction is completed. — **To File** – The message is not transmitted, but written to a file instead. — **Network** – Transmission via IP over a network. **Port Settings*** — **Baud Rate, Parity, Data Bits** and **Stop Bits.** — **Checksum** – Returns a confirmation of transmission message between computers. — **Delimited** – Transmits data in Comma Delimited Format. — **Multicast** – Method of networking scale weight information to other FB3000 II instruments across a Network. — **Map View** – Displays data in a memory mapped location. ▪ *The* **Testapp.exe,** *located in th***e Kernel folder,** *is used to verify memory mapped data,* — **Output to PC104** – Sends data to optional PC 104 Weight Controller Card using the **20mA** or **4-20mA outputs.** **Software Hand Shaking –** A means to control data flow using software functions for communication between two or more devices. — **None –** Bits are sent to source computer constantly without waiting for available receiving modem. — **Both, Receive or Transmit** – Determines which computer(s) wait to accept the message packets.

4.2.9. Other Data String Customization, Continued



Window Name	Description
CONFIGURE OUTPUT, CONTINUED — **Settings Tab, Continued**	**Hardware Hand Shake –** A means to control data flow using hardware functions for communication between two or more devices. **Network Controls** — **DTR (Data Terminal Ready)** – A control signal that indicates that the Data Terminal Equipment (DTE) is ready for data transmission. — **RTS (Request To Send)** – A control line which receives a verification signal from the CTS Control Line when it is ready to send data.

4.2.9. Other Data String Customization, Continued





Window Name	Description
CONFIGURE OUTPUT, CONTINUED — **[Port] Settings Tab** ❶	**Control Signals** — **DSR (Data Set Ready) –** A control signal that indicates the device is ready to transmit data. — **CTS (Clear To Send) –** A control signal used to notify the device that it has line control.
— **Load Tab** ❷	Selects a preconfigured data protocol based on the scale manufacturer selected. — Select this item first when configuring an output. — Press the **OK** button to load the data protocol selected.

DEFAULT DATA PROTOCOLS

Fairbanks	**<STX><A><B><C><GGGGGG><TTTTTT><CR>**
Toledo	**<STX><A><B><C><GGGGGG><TTTTTT><CR>**
Cardinal	**<CR><P><WWWWWW><m><SP><U><SP><g><SP><SP><ETX>**
Weightronix	**< ><M><WWWWWW>< ><U><CR><LF>**
Condec	**<STX><P><WWWWWWW><U><G><M><CR>**

*** See* **Appendix III** *for more formatting information.*

4.2.9. Other Data String Customization, Continued



Window Name	Description
CONFIGURE OUTPUT, CONTINUED — **Tokens Tab**	Programs the various data string tokens, such as the **Motion** flag. Tokens are setup for the data protocol requirements. **Wrappers** — **Poll** – Polling character for a **demand output.** ▪ *Applicable only to the Demand Mode.* — **Start** – The **first character** of a data string. — **Stop** – The **last character** of a data string. — **Block** – The character that **separates the data fields.**
	Units – The character(s) used to define the unit of measure in the data string — **Primary** – The **main indicator** unit of measure. — **Secondary** – The **alternate indicator** unit of measure.
	Mode – The character(s) used to define the **Weighing Mode** in the data string. — **Gross** – Character(s) used to designate the **gross weight.** — **Tare** – Character(s) used to designate the **tare weight.** — **Net** – Character(s) used to designate the **net weight.**

4.2.9. Other Data String Customization, Continued



Window Name	Description
CONFIGURE OUTPUT, CONTINUED — **Tokens Tab**	**Status – Identifies invalid weight conditions.** — **Motion** – Character(s) used to identify the scale weight is **in motion.** — **Capacity** – Character(s) used to identify the scale weight is **over capacity** — **OK** – Character(s) used to identify the scale **weight is valid.** — **Invalid** – Character(s) used to identify the scale weight is **invalid.**

4.2.9. Other Data String Customization, Continued





Window Name	Description
CONFIGURE OUTPUT, CONTINUED — **Status Codes Tab** ❶	Programs data bits for **Status Words A, B** and **C within the Fairbanks and Toledo data streams**. — **Status Word** is eight **(8) bits** long. 22. Put the **Status Words** in the blank **Data Entry Position**. 23. Press the **Loaded it** button.
— **Weights Tab** ❷	Programs specific values for the Weight Tokens. — **Weighing Digits** – Programs the length of the weight data. ▪ *Typically **six or seven digits** in length.* — **Leading Zeros** – When checked, adds leading zeros to the weight data. — **Justification** – Right or left. — **Decimal Point** – None, Floating, Fixed, Trailing. — **Fixed Decimal Places –** Sets number of decimal places in weight data string. — **Test Weight** – A manual weight entry to test data output. **Polarity – When** checked, it places a polarity token in front of the weight data item. — **Positive Token** – (**+**), None or Space — **Negative Token** – (**–**), None or Space

4.3. 20 MA SERIAL CURRENT LOOP PROGRAMMING

Procedure steps skipped or omitted during this process may cause certain features to not operate or function as expected. The 20 mA output is passive.

Note: *The PC104 Weight Controller Kit (27104) must be installed for this output to be available.*

Procedure:

1. In the **Kernel Weighing Program**, click the **MENU** button to open the Configuration Menu.

2. Open the **Remote Display**.



4.3. 20mA Serial Current Loop Programming, Continued

3. Set the **Remote Display** to **COM 1**.
4. Configure the **Baud**, **Parity**, **Data Bits**, and **Stop Bits** required.
5. Reset the **Remote Display** back to **OFF**.
6. Select the **Enable 20ma Output** check option.
7. Select **ACTIVE** in the **Scale** dropdown window.
8. Select **Continuous** in the correct drop-down window.





4.4. IP NETWORK OUTPUT

4.4.1. P Setup Menu Overview.



Window Name	Description
CONFIGURE OUTPUT — **IP Setup Tab**	**IP Port Settings** • **Local Port** – The socket number on the local FB3000 II used to transmit and receive data. • **Remote Port** – Set to the same socket number as the Local Port in which the remote transmits and receives data. • **Remote Host** – The IP Address of the Remote Host • **TimeOut** – The amount of time lapses before it is disconnected. • **Keep Alive** – Keeps the connection active. ✓ **Default Setting = False.** • **Linger** – When set to **True**, connections are terminated gracefully. ✓ **Default Setting = False.** Test Connection Verifies connectivity or connection.

NOTE: *See Appendix IV for complete information regarding* **SOCKS Protocol.**

4.4.1. IP Setup Menu Overview, Continued



Window Name	Description
CONFIGURE OUTPUT, CONTINUED — **IP Setup Tab**	**Firewall Settings** • **Host** – The Host IP Address. • **Port** – The Port Socket number used. • **Type** ✓ **Default = No Firewall.** — **Tunnel** – Set to 80. — **SOCKS4*** – Set to 1080. — **SOCKS5*** – Set to 1080. • **User** – User Login name • **Password** – User Password to login to the Host. • **Connect** – Establishes a connection. Terminates all active connections. Show a log of all IP events. Stop Listening Stops the monitoring signal with the scale.

* *See* **Appendix IV** *for complete information regarding* ***SOCKS Protocol.***

4.4.2. IP Network Output Setup Instructions

The following procedure outlines the setup instructions required to activate the **IP NETWORK** output function. Procedure steps skipped or omitted during this process may cause certain features to not operate or function as expected.

Follow these steps to configure the **IP Network Output**.

9. From the **Weighing Application Window**, press the **MENU** button, from the Kernel Options Menu, select **Configuration Menu**.

10. Select **Configure Output**..



4.4.2. IP Network Output Setup Instructions, Continued

11. Select an unused **COM Port** to be configured. Example: COM 5.
12. Access the **Load** tab and select a default format similar to what is required.
13. Press the ✓OK button.

.



14. Select the **Build** tab and configure the data output format as desired.



4.4.2. IP Network Output Setup Instructions, Continued

15. Use the **Mode** drop down list to select the **Network** mode.

16. Select the **IP Setup** tab to configure the network parameters. Pointing to each edit box will display a brief help message, to assist in the setup

17. Program the **IP Port Settings**. by setting the **Local Port** and the **Remote Port** to the same number as appropriate for the users network.

    Example: port = 2000.



- Set the **Remote Host** to one of the following
  - The IP address of the remote computer which will receive the weight data,
  - The network computer name of the remote computer which will receive the weight data as in the example shown above.

18. **Firewall Settings** – Leave the defaults as shown

19. The customer will need to provide a receiving application on a network computer which will open a connection through a TCP/IP socket with

    - The IP address must be set to the address of the FB3000 II and the Port set to the FB3000 II **Local Port** setting. Example: 2000.
    - When the IP is configured correctly, it will display **Listening**.



20. The data steam will be a continuous stream in the format set in step 6 above.

4.4.3. Testing the IP Network Output

Test Instructions to activate the **IP Network Output** function from the FB3000 II Kernel Weight Server program.

1. Setup the **IP Network Output** as described in Section 7.6.2. of this manual.
2. Return the Kernel back to the **Weight Processing Screen**.
3. At a different computer on the same network, use Hyper-Terminal to receive the data.
4. Start Hyper-Terminal, enter a **New Connection** name. Example: Test. Click OK.
5. Set the **Connect Using** drop down box to **TCP/IP (Winsock).**
7. Set the **Host Address** to the **IP address** of the computer or FB3000 II that the Kernel.exe is running on.
7. Set the **Port Number** to the same value as the **Local port** is set.
8. Click OK. If a connect attempt is made, it will fail at this point, ignore and clear the error message.
9. Select the **Call** menu item and select **Wait for Call** from the drop down menu.
10. If all is working, the instrument should make connection and weight data should be displayed in the Hyper-Terminal window in the format set previously in the setup instructions

Section 5: Operation

5.1. SYSTEM BOOT-UP PROCEDURE

Initiate the power up sequence using the power **ON/OFF** rocker switch located on the **bottom-left side** of the instrument.

Normal indications include the following:

- Lights on the keyboard should blink.
- After approximately **one minute**, the **Fairbanks Logo** appears along with a mouse pointer, located approximately in the center of the screen.

- The **Fairbanks Logo** disappears.
- A Windows welcome screen appears.
- Lastly, a weighing application window appears.

5.2. VIEWING OPTIONS



*The **GTN Screen** application*



*The Multi-Scale **Screen** application*

When using the **Kernel Program**, there are **two viewing options** for weighing.

The GTN Screen

The **GTN Screen** displays the weighments for only .one scale at a time.

Multi-scale Screen

The **Multi-scale Screen** displays all configured scales on the screen at one time.

- The Golden Diamond show which weighment is being used
- The scale being used is identified in the lower-left corner of the screen.

5.3. GROSS WEIGHING

1. Press the **ZERO** key to zero the scale.
2. Place the object to be weighed on the platform.
3. View the weight from the screen.

NOTE: *The* **Operating Mode** *is* ***Service-Programmable only****.*

5.3.1. Using the Display Screen Function Buttons

- When in the **Multi-scale Screen**, press the **F1 button** to toggle thru the available scales.
- Press the *display screen's* **F6 button** to toggle back-and-forth from the GTN Screen to the Multi-scale Screen.

5.4. APPLICATION SHUT-DOWN PROCEDURE

1. To close the **Kernel Program**, press the **Exit** button on the open weighing application screen.

2. Double-click on the **Exit Application** button.



C A U T I O N

Improper shutdown of this instrument can cause damage to the hard drive and loss of data.

5.5. SYSTEM SHUTDOWN PROCEDURE

C A U T I O N

Improper shutdown of this instrument can cause damage to the hard drive and loss of data.

1. Using the external keyboard, press and hold the **ALT + F4** keys simultaneously to exit the program.

The FB3000 II will close down properly.

2. Click the **Turn Off** button.
   - The instrument turns off.
   - Upon shut down, the display turns dark.



3. Turn off the power using the **ON/OFF** rocker switch.

Section 6: SERVICE & MAINTENANCE

IMPORTANT PRECAUTIONS

Electrostatic Discharge (**ESD**) can easily damage the FB3000 II board assemblies. Do not touch or handle internal components without proper precautions such as utilizing a grounding strap.

6.1. TROUBLESHOOTING

Error Condition(s)	Solution(s)
• **Check that scale is empty.** • **If Scale is empty, Call for Service.** • **Load Cell(s) bad.**	• A large amount of weight is zeroed. • This is **normal.** • Press **OK** and continue weighing. • Possible load cell damage. • Call for Service.
• **Load Cell Failure(s)** • **Flashing and displays "- - - -"**	• Possible load cell damage. • Call for Service. • Access the **Load Cell Diagnostics Menu** to verify the load cell status. • Count stability or change of counts. • Contact the local service for further trouble-shooting.
SC Cells Found None	• Possible damaged load cell cable. • Load cell shortened. • Defective Pit Power Supply. • Defective Smart Sectional Controller(s). • Defective Analog Assembly. • Call for Service.
Displays " - - - - " ~ lb GROSS	• Communication error to load Cells. • Call for Service.

6.2. REMOTE SERVICE AND DIAGNOSTICS

The FB3000 II can be serviced and have diagnostics performed from a remote location, such as the nearest **authorized Fairbanks Service Center**.

- The instrument must be connected to a network with internet access.
- The **Remote VNC Connection** can be programmed to display in the **Weight Window** or in the **minimized tray**.

6.2.1. Opening the VNC Connection

1. To open the remote connection, left-click on the **Fairbanks Globe**.
2. Click the **Menu** key.
3. Give the Remote Fairbanks Technician the **IP address** listed within the **Remote Diagnostic Mode Window.**
4. Upon completion of diagnostics, the Remote Fairbanks Technician will disconnect at his or her end.

5. Disconnect the **Remote VNC Connection** by clicking the box.
   – This returns the Kernel Program back to normal operations.

Appendix I: GPIO Port

Programming the GPIO Port

The FB3000 II provides an 8-bit GPI port and an 8-bit GPO port that you can use to read and write data through.

Reading the GPIO Data

- 2e,87
- 2e,87
- 2e,2a //configuration register(CR2a)
- 2f,fc //set GPIO ,not GAME PORT
- 2e,07 //point to logical device number reg
- 2f,07 //select logical device 7
- 2e,30 //configuration register(CR30)
- 2f,1 //open logical device control
- 2e,f0 //configuration register(CRf0)
- 2f,FF // 1=input
- 2e,f1
- I 2f // read value (00 ~ FF)

Writing the GPIO Data

- 4e,87
- 4e,87
- 4e,2a //configuration register(CR2a)
- 4f,fc //set GPIO ,not GAME PORT
- 4e,07 //point to logical device number reg.
- 4f,07 //select logical device 7
- 4e,30 //configuration register(CR30)
- 4f,1 //open logical device control
- 4e,f0 //configuration register(CRf0)
- 4f,00 // 0=output
- 4e,f1
- 4f,XX // XX= (00 ~ FF) output value

bit0 : GPI(O)1 bit1 : GPI(O)2 bit2 : GPI(O)3 bit3 : GPI(O)4 bit4 : GPI(O)5 bit5 : GPI(O)6 bit6 : GPI(O)7 bit7 : GPI(O)8

Appendix II: System Resource

Interrupt Controller

The FB3000 II embedded PCB is a fully PC compatible control board. It consists of 16 ISA interrupt request lines. Most of them are already in use by other parts of the board. Both ISA and PCI expansion cards may need to use IRQs, so make sure the IRQs do not conflict when using add-on cards.

System IRQs are available to cards installed in the ISA expansion bus first. Any remaining IRQs then may be assigned to the PCI bus. **Check out an AMI diagnostic utility to see the map.**

IRQ	Assignment
IRQ0	System Timer Output
IRQ1	Keyboard
IRQ2	Interrupt rerouting from IRQ8 through IRQ15
IRQ3	Serial Port 2
IRQ4	Serial Port 1
IRQ5	Serial Port 4
IRQ6	Serial Port 3
IRQ7	Parallel Port
IRQ8	Real Time Clock
IRQ9	Reserved
IRQ10	Reserved
IRQ11	Reserved
IRQ12	PS/2 Mouse
IRQ13	Math Coprocessor
IRQ14	Primary IDE Controller
IRQ15	Secondary IDE Controller

Shared Memory (Kernel Mapped Output)

```
//***********************************
// Sample code to read Kernel Mapped Output (Shared Memory)
//***********************************
//   FileMap Memory Structure
struct FileMapStruct
        {
        unsigned char   data[256];       // configured output string from kernel
        unsigned char   command[2];    // command to return to kernel i.e. “z” = zero all scales, “Z1” =
        zero scale 1
        int     length;                  // length of string in data
        int     counter;                 // sequential number
        char    status[128];              // kernel status
};

bool TScaleForm::ReadMappedOutput(char *input)
{
    bool   result = false;
    bool   CommandSent = false;

    if( MappedOutputHandle == NULL )
    {
     wSemaphore = CreateSemaphore(NULL, 1, 1, “Output1 Write");
        if( wSemaphore == NULL )
       return 0;
     rSemaphore = CreateSemaphore(NULL, 0, 1, “Output1 Read");
         if( rSemaphore == NULL ) {
       CloseHandle(wSemaphore);
       wSemaphore = NULL;
        return 0;
      }
```

Shared Memory (Kernel Mapped Output), Continued

```
MappedOutputHandle = CreateFileMapping((HANDLE)0xFFFFFFFF, NULL,
    PAGE_READWRITE,
  0,
  sizeof(struct FileMapStruct),
  “Output1”);

    if( MappedOutputHandle == NULL )
 {
    CloseHandle(rSemaphore);
    rSemaphore = NULL;
    CloseHandle(wSemaphore);
    wSemaphore = NULL;
    return 0;
    }
}
if( MapOutputData == NULL ) {
  MapOutputData = (struct FileMapStruct*)MapViewOfFile(MappedOutputHandle,
  FILE_MAP_WRITE,
   0, 0,
  sizeof(struct FileMapStruct));
}
if( MapOutputData != NULL )
  {
    // wait for kernel to release
    if( WaitForSingleObject(rSemaphore, 5) == WAIT_FAILED )
    return false;
    // Check Counter to see if Kernel has sent a new string
    if( MapOutputData->counter != LastCounter )
```

Shared Memory (Kernel Mapped Output), Continued

```
{
            LastCounter = MapOutputData->counter;
            int len = MapOutputData->length;
            if( len >  sizeof(MapOutputData->data)-1 )
                 len = sizeof(MapOutputData->data)-1;

            ScaleStatus_Text->Caption = (String)MapOutputData->status;
            input[0] = NULL;
            for ( int mf = 0; mf < len; mf++ ) {
                 input[mf] = MapOutputData->data[mf];
        }
        input[len] = NULL;
         // return command i.e. 'z' to zero scales, 'u' to change units etc… (2 char buffer… 'Z1' to zero
         scale 1)
        if( KernelCommand[0] != NULL )
           {
           MapOutputData->command[0] = KernelCommand[0];
           MapOutputData->command[1] = KernelCommand[1];
           KernelCommand[0] = NULL;
           CommandSent = true;
         }
             result = true;
         }
        // release semaphore for kernel
         ReleaseSemaphore(wSemaphore, 1, NULL);
   }
   return result;
}
//---------------------------------------------------------------------------
```

Appendix III: Data Output

REMOTE DISPLAY OUTPUT

Data Format

<STX><4><0><SP/-><XXXXXX><ETX>

Note(s):

1. *Characters denoted by* **X** *are* **characters 0-9.**
2. *Leading zeroes are suppressed.*
3. *Polarity indication for a positive value is a space (***SP***).*
   – *Negative values are not transmitted.*
4. **Identifier code <4><0> = Gross weight***.*
   – *Transmission is* **Gross Only***.*
5. *Transmission for the* **DEMAND Mode** *occurs when a carriage return* **(CR) Hex 0D** *is received.*

CONFIGURE OUTPUT

Fairbanks Data Format

<STX><A><B><C><GGGGGG><TTTTTT><CR>

Note(s):

1. *Characters denoted by* **G** *and* **T** *are* **characters 0-9***.*
2. *Leading zeroes are suppressed.*
3. ***Gross Weight Data*** **= G**
   Tare Weight Data **= T**

Status Code (Word) A

Bit #	X00	X0	X	X.X	X.XX	X.XXX	X.XXXX	X.XXXXX
0	0	1	0	1	0	1	0	1
1	0	0	1	1	0	0	1	1
2	0	0	0	0	1	1	1	1

CONFIGURE OUTPUT, CONTINUED

Increment Size

Bit #	Count By 1	Count by 2	Count by 5
3	1	0	1
4	0	1	1
5		Always Logic 1	
6		Always Logic 0	
7		Parity Bit	

Status Code (Word) B

Bit #	Description		
0	Gross = 0		Net = 1
1	Positive = 0		Negative = 1
2	In Range = 0		Overcapacity = 1
3	No Motion = 0		Motion = 1
4	Lb = 0		Kg = 1
5	Always Logic 1		
6	Normal = 0		Power Up = 1
7	Parity Bit		

Status Code (Word) C

Bit #	Description		
0	Always Logic = 0		
1	Always Logic = 0		
2	Always Logic = 0		
3	Normal = 0		Print Switch Pushed = 1
4	Always Logic = 0		
5	Always Logic = 0		
6	Normal = 0		Keyboard Tare = 1
7	Parity Bit		

Toledo Data Format

<STX><A><B><C><GGGGGG><TTTTTT><CR>

Note(s):

1. Characters denoted by **G** *and* **T** *are* **Characters 0-9***.*

2. Leading zeroes are ***not suppressed****.*

3. ***Gross Weight data = G***

Tare Weight data = T

Status Code (Word) A

Bit #	X00	X0	X	X.X	X.XX	X.XXX	X.XXXX	X.XXXXX
0	0	1	0	1	0	1	0	1
1	0	0	1	1	0	0	1	1
2	0	0	0	0	1	1	1	1

Increment Size

Bit #		Count By 1		Count by 2		Count by 5
3		1		0		1
4		0		1		1
5				Always Logic 1		
6				Always Logic 0		
7				Parity Bit		

Toledo Data Format, Continued

Status Code (Word) B

Bit #	Description			
0		Gross = 0		Net = 1
1		Positive = 0		Negative = 1
2		In Range = 0		Overcapacity = 1
3		No Motion = 0		Motion = 1
4		Lb = 0		Kg = 1
5		Always Logic = 0		
6		Normal = 0		Power Up = 1
7		Parity Bit		

Status Code (Word) C

Bit #	Description			
0		Always Logic = 0		
1		Always Logic = 0		
2		Always Logic = 0		
3		Normal = 0		Print Switched Pushed = 1
4		Always Logic = 0		
5		Always Logic = 1		
6		Normal = 0		Keyboard Tare = 1
7		Parity Bit		

Cardinal 738 Continuous Scoreboard Data Format

<CR><P><WWWWWW><m><SP><U><SP><g><SP><SP><ETX>

Note(s):

1. *W = Displayed weight*
   P = Polarity
   + = Positive weight
   - = Negative weight
   U = Units
   lb = pounds
   kg = kilograms
   m = Motion or o = Overload
   g = Gross; n = Net
   SP = Space
2. *Leading zeros are not suppressed.*

Weightronix Data Format

< ><M><WWWWWW>< ><U><CR><LF>

Note(s):

1. *< > = Space*
   M = Mode
   G =Gross
   T=Tare
   N=Net
   W = Displayed weight
   U = Units
   m = Motion
   o = Overload
2. *Leading zeros are suppressed.*

Condec Continuous Data Format

<STX><P><WWWWWW><U><G><M><CR>

Note(s):

1. *P = Polarity*
   space = positive weight
   - = negative weight
   W = Displayed weight
   U = Units
   L = pounds
   K = kilograms
   G = Gross; N = Net
   M = Motion
2. *Leading zeros are suppressed.*

Build Tab Definitions

Load Cell Status <L> This item, if included in the data output string, indicates if a load cell(s) are indicating an error. If no error is present, a zero (0) will be present or the character equivalent of the decimal number of load cell with an error will be indicated. i.e. 1 = <SOH>, 28 = <FS>

Appendix IV: Network Command Functions

Command Structure:

[**Sender**],[**COMMAND**],**Command**,[**End**][**LF**]

Where **Sender** is:

The Computer Name of the PC which is sending the command.

Where Command is:

Lowercase z =	Zeroes all scales.
Uppercase Z1, Z2, etc =	Zero a specific scale.
Uppercase ZA or ZB =	Zero Group ScaleA (1 to 4) or Group ScaleB (5 to 8).
Uppercase Txxxxx =	Apply Tare xxxxx to Active scale where xxxxx = Tare value.
Uppercase T#,xxxxx =	Apply Tare xxxxx to Selected scale # where xxxxx = Tare value and # = Scale number.
Uppercase A =	Auto Tare Active scale
Lowercase u =	Change units on all scales.
Uppercase U1, U2, etc. =	Change units on a specific scale.
Uppercase UA or UB =	Change units on Group ScaleA (1 to 4) or Group ScaleB (5 to 8).
Uppercase S# =	Make Scale # (1-8) the Active scale where # = Scale number.

Poll Character (see Configured Output) sends configured output.

LF =	Line Feed

Example:

[Freds PC],[COMMAND],Z1,[End][LF]

i.e. – Freds PC is requesting Scale 1 to Zero.

Appendix V: Programming the Watchdog Timer

The **FB3000 II Embedded PCB** provides a Watchdog Timer that resets the CPU or generates an interrupt if processing comes to a stop.

- This function ensures greater system reliability in industrial standalone and unmanned environments.
- ***T o enable the Watchdog Timer***, output the value of the Watchdog Timer Interval to the Controller.
- The value range is from **01H to FFH**, and the related time Watchdog Timer interval is **one (1) second to 255 seconds**.

DATA	TIMER INTERVAL
00	Disabled
01	One (1) second
02	Two (2) seconds
*	*
*	*
FF	255 seconds

NOTE: *To program the* **Watchdog Timer***, write the timer value to the* **I/O Port 444 (hex).**

Example: **Assembly Language**

Start Watchdog Timer	DOS Debug
MOV DX, 444H	OUT 444, XX
MOV AL, XXH	
OUT DX, AL	

Start Watchdog Timer	DOS Debug
MOV DX, 444H	IN 441
IN AL, DX	

Appendix VI: Kernel 20mA Codes

Code	Units	Data Displayed	Scale #
00		**Display all data.**	
40	lbs	Gross	1
41	lbs	Net	1
42	lbs	Tare	1
43	kg	Gross	1
44	kg	Net	1
45	kg	Tare	1
46	lbs	Gross	2
47	lbs	Net	2
48	lbs	Tare	2
49	kg	Gross	2
50	kg	Net	2
51	kg	Tare	2
52	lbs	Gross	3
53	lbs	Net	3
54	lbs	Tare	3
55	kg	Gross	3
56	kg	Net	3
57	kg	Tare	3
58	lbs	Gross	4
59	lbs	Net	4
60	lbs	Tare	4
61	kg	Gross	4
62	kg	Net	4
63	kg	Tare	4
64	lbs	Gross	5
65	lbs	Net	5
66	lbs	Tare	5
67	kg	Gross	5
68	kg	Net	5
69	kg	Tare	5
70	lbs	Gross	6
71	lbs	Net	6
72	lbs	Tare	6
73	kg	Gross	6
74	kg	Net	6
75	kg	Tare	6
76	lbs	Gross	7
77	lbs	Net	7
78	lbs	Tare	7
79	kg	Gross	7
80	kg	Net	7
81	kg	Tare	7
82	lbs	Gross	8
83	lbs	Net	8
84	lbs	Tare	8
85	kg	Gross	8
86	kg	Net	8
87	kg	Tare	8
99	**lbs**	**TOTAL**	**For FB3000 II HWY SYS**

** Existing 2500 output (excluding HWY SYS application*

Appendix VII: SOCKS Information

SOCKS is an Internet Protocol that allows client-server applications to transparently use the services of a network firewall.

- **SOCKS** is an abbreviation for “sockets”.
- Clients behind a firewall, needing to access exterior servers, may connect to a SOCKS proxy server instead. Such a proxy server controls the eligibility of the client to access the external server and passes the request on to the server.
- **SOCKS** can also be used in the opposite way, allowing the clients outside the firewall (exterior clients) to connect to servers inside the firewall (internal servers).

A typical **SOCKS 4** connection request looks like the following (each number is one byte).

Client to SOCKS Server:

- **Field 1:** SOCKS version number, 1 byte, must be 0x04 for this version
- **Field 2:** Command code, 1 byte:
  - **0x01 =** Establish a TCP/IP stream connection.
  - **0x02 =** Establish a TCP/IP port binding.
- **Field 3:** Network byte order port number, 2 bytes.
- **Field 4:** Network byte order IP address, 4 bytes.
- **Field 5:** The user ID string, variable length, terminated with a null (0x00).

Server to SOCKS client:

- **Field 1:** Null byte.
- **Field 2:** Status, 1 byte:
  - **0x5a =** Request granted.
  - **0x5b =** Request rejected or failed.
  - **0x5c =** Request failed because client is not running identd (or not reachable from the server).
  - **0x5d =** Request failed because client’s identd could not confirm the user ID string in the request.
- **Field 3:** 2 arbitrary bytes, that should be ignored.
- **Field 4:** 4 arbitrary bytes, that should be ignored.

APPENDIX VII: SOCKS INFORMATION, CONTINUED

The **SOCKS** 5 Protocol, an extension of the **SOCKS 4 Protocol** that offers more choices of authentication, is defined in **RFC 1928**.

The initial handshake now consists of the following:

- Client connects and sends a greeting which includes a list of authentication methods supported.
- Server chooses one (or sends a failure response if none of the offered methods are acceptable).
- Several messages may now pass between the client and the server depending on the authentication method chosen.
- Client sends a connection request similar to SOCKS 4.
- Server responds similar to SOCKS 4.

The authentication methods supported are numbered as follows:

- **0x00 –** No authentication.
- **0x01 –** GSSAPI.
- **0x02 –** Username/Password.
- **0x03-0x7F –** Methods assigned by IANA.
- **0x80-0xFE –** Methods reserved for private use.

The initial greeting from the client is:

- **Field 1:** SOCKS version number (must be 0x05 for this version).
- **Field 2:** Number of authentication methods supported, 1 byte.
- **Field 3:** Authentication methods, variable length, 1 byte per method supported.

The server's choice is communicated:

- **Field 1:** SOCKS version, 1 byte (0x05 for this version).
- **Field 2:** Chosen authentication method, 1 byte, or 0xFF if no acceptable methods were offered.

APPENDIX VII: SOCKS INFORMATION, CONTINUED

The subsequent authentication is method-dependent and described in **RFC 1929.**

The client's authentication request is:

- **Field 1:** Version number, 1 byte (must be 0x01).
- **Field 2:** Username length, 1 byte.
- **Field 3:** Username.
- **Field 4:** Password length, 1 byte.
- **Field 5:** Password.

Server response for authentication:

- **Field 1:** Version, 1 byte.
- **Field 2:** Status code, 1 byte.
  - **0x00 =** success.
  - **Any other value =** failure, connection must be closed.

The client's connection request is:

- **Field 1:** SOCKS version number, 1 byte (must be 0x05 for this version).
- **Field 2:** Command code, 1 byte:
  - **0x01 =** establish a TCP/IP stream connection.
  - **0x02 =** establish a TCP/IP port binding.
  - **0x03 =** associate a UDP port.
- **Field 3:** Reserved, must be 0x00.
- **Field 4:** Address type, 1 byte:
  - **0x01 =** Ipv4 address.
  - **0x03 =** Domain name.
  - **0x04 =** Ipv6 address.
- **Field 5:** Destination address of:
  - 4 bytes for Ipv4 address.
  - 1 byte of name length followed by the name for Domain name.
  - 16 bytes for Ipv6 address.
- **Field 6:** Port number in a network byte order, 2 bytes.

APPENDIX VII: SOCKS INFORMATION, CONTINUED

Server response:

- **Field 1:** SOCKS protocol version, 1 byte (0x05 for this version).
- **Field 2:** Status, 1 byte:
  - **0x00 =** Request granted.
  - **0x01 =** General failure.
  - **0x02 =** Connection not allowed by ***ruleset***.
  - **0x03 =** Network unreachable.
  - **0x04 =** Host unreachable.
  - **0x05 =** Connection refused by destination host.
  - **0x06 =** TTL expired.
  - **0x07 =** Command not supported / protocol error.
  - **0x08 =** Address type not supported.
- **Field 3:** Reserved, must be 0x00.
- **Field 4:** Address type, 1 byte:
  - **0x01 =** Ipv4 address.
  - **0x03 =** Domain name.
  - **0x04 =** Ipv6 address.
- **Field 5:** Destination address of :
  - 4 bytes for Ipv4 address.
  - 1 byte of name length followed by the name for Domain name.
  - 16 bytes for Ipv6 address.
- **Field 6:** Network byte order port number, 2 bytes.

Appendix VIII: Remote Functions

Hardware Connections

REMOTE FUNCTIONS	CN14	
Remote Zero Switch	3	11 or 12
Remote Print Switch	9	11 or 12

**Dry contacts only.*

***Must have I/O accessory installed.*

Remote Software Commands using Serial Port/ Mapped Memory/ Multicast

FUNCTION	SOFTWARE COMMAND
Zero Active Scale	Z
Zero ALL Scales	z
Zero a Specific Scale	Z# where # is the Scale number.
Zero Scales 1-4	ZA
Zero Scales 5-8	ZB
Set Tare on Active Scale	Txxxxx where xxxxx is the Tare weight value.
Set Tare on a Specific Scale	T#, xxxxx where # is the Scale number and xxxxx is the Tare weight value.
AutoTare on Active Scale	A
Change Units on Active Scale	U
Change Units on ALL Scales	u
Change Units on Specific Scale	U# where # is the Scale number.
Print Active Scale	P
Change to Multi-Screen	m
Change to GTN Screen	g
Select Active Scale	S# where # is the Scale number.

APPENDIX IX: ASCII CODES

HEX	DEC	CHAR
00	000	NUL
01	001	SOH
02	002	STX
03	003	ETX
04	004	EOT
05	005	ENQ
06	006	ACK
07	007	BEL
08	008	BS
09	009	HT
0A	010	LF
0B	011	VT
0C	012	FF
0D	013	CR
0E	014	SO
0F	015	SI
10	016	DLE
11	017	DC1
12	018	DC2
13	019	DC3
14	020	DC4
15	021	NAK
16	022	SYN
17	023	ETB
18	024	CAN
19	025	EM
1A	026	SUB
1B	027	ESC
1C	028	FS
1D	029	GS
1E	030	RS
1F	031	US
20	032	SPACE
21	033	!
22	034	"
23	035	#
24	036	$
25	037	%
26	038	&
27	039	5
28	040	(
29	041	)
2A	042	*

HEX	DEC	CHAR
2B	043	+
2C	044	,
2D	045	-
2E	046	.
2F	047	/
30	048	0
31	049	1
32	050	2
33	051	3
34	052	4
35	053	5
36	054	6
37	055	7
38	056	8
39	057	9
3A	058	:
3B	059	;
3C	060	<
3D	061	=
3E	062	>
3F	063	?
40	064	@
41	065	A
42	066	B
43	067	C
44	068	D
45	069	E
46	070	F
47	071	G
48	072	H
49	073	I
4A	074	J
4B	075	K
4C	076	L
4D	077	M
4E	078	N
4F	079	O
50	080	P
51	081	Q
52	082	R
53	083	S
54	084	T
55	085	U

HEX	DEC	CHAR
56	086	V
57	087	W
58	088	X
59	089	Y
5A	090	Z
5B	091	]
5C	092	\
5D	093	[
5E	094	^
5F	095	--
60	096	'
61	097	a
62	098	b
63	099	c
64	100	d
65	101	e
66	102	f
67	103	g
68	104	h
69	105	i
6A	106	j
6B	107	k
6C	108	l
6D	109	m
6E	110	n
6F	111	o
70	112	p
71	113	q
72	114	r
73	115	s
74	116	t
75	117	u
76	118	v
77	119	w
78	120	x
79	121	y
7A	122	z
7B	123	{
7C	124	|
7D	125	}
7E	126	~
7F	127	DEL

Manufactured by Fairbanks Scales, Inc.
821 Locust
Kansas City, Missouri 64106
www.fairbanks.com

FB3000 II KERNEL

OPERATOR MANUAL

DOCUMENT 51220